



H81M-C Repair Guide

07/162013
Leilei52_Chen
CSC-GRMA


BLOCK DIAGRAM



POWER FLOW




Frequency Flow



Voltage Measure Point

multi meter “V Ω mA” port touch here

Pink number is Diode resistance to GND(without any part on MB)multimeter type DH-1240



Signal Measure Point

