





## SUPER I/O



# DC Jack/1394



www.aitech1.ru

## Change note:

1. Change PJ2 and CN3 Part Number
2. Populate bead BK1608HM121 L1 to L7 in serial port
3. Add 180 pF C25 to C32 parallel connection to serial port