





BLOCK DIAGRAM




POWER FLOW



POWER ON SEQUENCE




CLKIN_SATA CLKOUT_PCIE2



Voltage Measure Point

multi meter "V Ω mA" port touch here

Pink number is Diode resistance to GND(without any part on MB)multimeter type DH-1240



Signal Measure Point

