




## P500CA BLOCK DIAGRAM



# POWER FLOW



www.aitech1.ru




## AC-IN Mode

## Power-On Sequence




## DC-IN Mode

## Power-On Sequence





# Signal Measure Point-Bottom





## Signal Measure Point-Top

