


BLOCK DIAGRAM

T100TA


Hall sensor

page:45


Block Diagram




POWER FLOW



POWER ON SEQUENCE



Signal Measure Point-Bottom



Signal Measure Point-Top

